
15262 Capitol Port San Antonio, TX 78249 1-833-877-0787 facadesxi.com

Xterior Insulation Masonry Veneer Assembly Termination at Balcony

Date: 06-15-2023 Detail.XIMVA.VI.2 v1



NOTES:

- 1. FXI WaterShield transition and accessory products and installation can be found in the project specifications, product datasheets and the WaterShield Details.
- 2. Drainage must be provided behind backwrap by either using a drainage transition or pre-wrap insulation boards.
- 3. High or Ultra High impact resistance is recommended on wall areas subjected to pedestrian traffic or other exposure to impact.
- 4. Non FXI products are shown for the clarity of the FXI products only.

DISCLAIMER: FACADESXi details are recommendations that should be used for guidance only. Inhere may be equivalent means of installation that are not shown in FACADESXi assembly details. All FACADESXi products shall be installed in accordance with FACADESXi product datasheets and all applicable building codes and industry standard practices. The design, engineering and final details incorporating any FACADESXi product are the sole responsibility of the project design professional FACADESXi is not responsible for determining the acceptability and/or applicability of any FACADESXi product or detail for any specific project or condition. IFACADESXI disclaims all liability for improper installation, workmanship,or design by a third-party.EXCEPT FOR ANY EXPRESS REPRESENTATIONS AND WARRANTIES BY FACADESXI, ALL IMPLIED WARRANTIES OF ANY KIND, INCLUDING BUT NOT LIMITED TO WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE OR COMPLIANCE WITH LAWS OR GOVERNMENT RULLES OR REGULATIONS APPLICABLE TO THE PROJECT, ARE HEREBY DISCLAIMED. FACADESXI's website should always be consulted for the latest version of any details and/or product information. Contact FACADESXI for any technical assistance.